

CASE STUDY

PARKS & RECREATION: SECURING SHELTER BATHROOMS

Park shelter bathrooms often become hotspots for vandalism, inappropriate activity, and after-hours misuse—especially in high-traffic public spaces with limited supervision. These facilities also present unique infrastructure challenges, as many lack existing connectivity to support traditional security systems.

To improve visibility and accountability, municipalities need targeted surveillance solutions that can adapt to each location's layout while helping deter unwanted behavior and support incident response.

ADDRESSING VANDALISM AND SAFETY CONCERNS

CHALLENGE

This high-traffic park experienced ongoing vandalism and inappropriate activity in parking areas and near restroom facilities. Without surveillance cameras, incidents were often discovered after the fact, limiting the municipality's ability to identify individuals or establish timelines.

SOLUTION

- H6A Dual Head Camera
- H5A Multisensor Camera

IMPACT

The new system provides broad coverage of the parking lot and surrounding areas, improving visibility into activity entering and exiting key locations. This allows staff and public safety personnel to:

- Deter vandalism and unwanted behavior
- Establish timelines for incidents
- Identify individuals associated with reported events
- Improve overall safety awareness in high-use public areas



Solution: H6A Dual Head Camera



Solution: H5A Multisensor Camera